

Revision Report

Prepared for: Customer Reference:

 Gefran Spa
 PO Number:
 1164500865

 Via Sebina, 74
 Date Submitted:
 May 08, 2017

Provaglio, d'Iseo (BS), 25050 Revision Request No: RR209655

Italy Class: 3545

www.gefran.com

Company ID 148244-1

Summary of Requested Changes for Application from Gefran Spa:

3054712 - PID temperature controllers/ 650&1250 - Errata corrige of manuals.

Summary of Changes From Your Application

Туре	Description	Project ID	Disposition	Comment
Technical Change	3054712 - PID temperature controllers/ 650&1250 - Errata corrige of manuals.	3054712	1 -	critical documents updated and L model documents added to CDL
Technical Change	3054712 - PID temperature controllers/ 650&1250 - Errata corrige of manuals.	3054712	1	650L and 1250L models to be added to approval guide, minor firmware changes separate L and original models

DATE: 13-Jun-17

PREPARED BY REVIEWED BY AUTHORIZED BY

Robert Deardorff David Waite James Marquedant

Engineer AVP, Technical Team Manager VP, Manager, Electrical Systems

Electrical Electrical Electrical

Technical Changes

1. Introduction

Addition of 650L and 1250L models, firmware differences do not affect performance

2. Listing

∃ Fuel & Combustion Controls **∃**Temperature Limit Switches **∃**Temperature Limit Switches --Indicating

Model No. 650L, 1250L

Temperature limit switches Model No. 650L, 1250LOperating Voltage 20...27Vac/dc or 100...240Vac/dc, Alarm Relays rated 5 A at 250 VAC